

Intersection: Calderon Ave at El Camino Real, Mountain View, California

MapData payload size 1053

```
payload=00128419280B30190000040600A5F6869791431F6708AA014A0288BC70B0045000000A40021CB6F0CA3AACE36
8579FB841C4D5E4522100008916200042C021400000100018741BC038EA0385C1D43702E3AD8E4345727C6459657A3E
C253EF7A70ECA7AA11080C00243100010600C8800000E00061DA82BC22BA5E3D159AF1D8AE03BE49428DC38595E0A2B
82538B7A28ED7BB681C042200000200008757CB428AF2B98C55979D80DA6850081C0016029A00000148004AFF58BC0C
0A0518743C5A0A86BAC26DCC8E4168B8DA8A852064000C916800062C0634000002000085EBCEA05A0C36BCF26C5C908
168D39A878122F0000C580E6800000400010BB25918B3F00D8844DD251802D1A7351C884220012310000C5810680000
0280012B9493E811E226268A928F7288970F2F7A4291040001486080008E04A100000100002BA001200121E0F8C8C21
D64FAC021500038148400000400018E8EE87516E3A2B93A203E209AC5A6105A47768EE089140040000101C702D08000
00800021D3C53565A0806BCE269E89869692CDA3EC2247001000004071C0C42000002000085AEA5D25A01E6BFE26B78
9401690C9A4C02249001000004072C0D540000009001D73071C706050288BDE20A0A35826FD40A13C099A09E2036C70
2D09E8DFBE3D1240361C1853B1F804849000196072A0000010001037D79A684D066A2276F2521C030A7E3814855C6FD
91FB1202A2F986FDB2968DEF07F42C013A7309043600021F000903800032C0F54000001000106E813AA899B8FC04F3A
65E27E101B2409E681031A5081230800063820C400000500030D6C895C136A13E89DC478890011DB24808CC342BFF6A
CFA120230D988FF910DE011180018116200000100004AF3BC0C441B607508FFA14CC5824E80000052001ACFF4FD40C0
A0518743C43176C191900AF084251AE3E2B0B549710A44080009215000045826E80000040001881D24548666D78431E
FDE788386DF1E563C291520485C0001160A3A00000100006213FA4221B855938C6A57F720C2980A1592FE43C8521900
0041158002C15740000014000943AD6C208F110D82AE1065FDB2D047F421148220002A46040014705A0800000800035
2AFF7D8243C5605E93961929EE80448F2892209E1882844220020000080A382F040000040001891477E8AC28F25E831
DE5FBC8924D1204156B0750884C00400001014706208000008000311AE6899583BE4D1C643CBB39124FA24C827CE1B0
211980088540040000101470660800000100022A843CFE084A63FD18F7AF0A42DCACCB008A080020D30004180001702
BCD5023C43C4BA93852364001C91D4000E041B60008300010F1853F81B231064251319A0DFD160291A4000B48E10005
820E30004000008745E13A0501F5011D0D4B0D18D47A148DA00052474800281075800200000233643350584FDA82D3C
E02148D100062471000300
```

gov.usdot.asn1.generated.j2735.dsrc.MessageFrame

```
value MessageFrame ::= {
  messageId 18,
  value MapData : {
    msgIssueRevision 11,
    layerType intersectionData,
    intersections {
      {
        id {
          region 0,
          id 1030
        },
        revision 0,
        refPoint {
          lat 373826607,
          long -1220776753,
          elevation 340
        },
        laneWidth 330,
        speedLimits {
          {
            type vehicleMaxSpeed,
            speed 559
          }
        },
        laneSet {
          {
            laneID 1,
            ingressApproach 1,
            laneAttributes {
              directionalUse {ingressPath},
              sharedWith {},
              laneType vehicle : {}
            },
            maneuvers {maneuverStraightAllowed, maneuverRightAllowed,
              maneuverRightTurnOnRedAllowed},
            nodeList nodes : {
              {
```

```

    delta node-XY4 : {
      x 731,
      y 2149
    }
  },
  {
    delta node-XY4 : {
      x 1369,
      y 2266
    }
  },
  {
    delta node-XY3 : {
      x 975,
      y 1474
    }
  },
  {
    delta node-XY2 : {
      x 550,
      y 377
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 16,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 4
  },
  {
    connectingLane {
      lane 22,
      maneuver {maneuverRightAllowed}
    },
    signalGroup 4
  }
}
},
{
  laneID 2,
  ingressApproach 1,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverLeftAllowed},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x 1051,
        y 2055
      }
    },
    {
      delta node-XY4 : {
        x 1281,
        y 2140
      }
    },
    {
      delta node-XY4 : {
        x 1293,

```

```

        y 2071
    }
},
{
    delta node-XY4 : {
        x 1457,
        y 2317
    }
},
{
    delta node-XY3 : {
        x 915,
        y 1586
    }
},
{
    delta node-XY6 : {
        x 5719,
        y 9196
    }
},
{
    delta node-XY5 : {
        x 2551,
        y 3918
    }
},
{
    delta node-XY4 : {
        x 1619,
        y 2721
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 1,
            maneuver {maneuverStraightAllowed}
        }
    },
    {
        connectingLane {
            lane 12,
            maneuver {maneuverLeftAllowed}
        },
        signalGroup 4
    }
}
},
{
    laneID 3,
    egressApproach 2,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed, maneuverLeftAllowed, maneuverRightAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x 1696,
                y 1505
            }
        }
    },

```

```

    {
      delta node-XY3 : {
        x 933,
        y 1597
      }
    },
    {
      delta node-XY3 : {
        x 821,
        y 1595
      }
    },
    {
      delta node-XY3 : {
        x 896,
        y 1785
      }
    },
    {
      delta node-XY5 : {
        x 2129,
        y 3612
      }
    },
    {
      delta node-XY6 : {
        x 5600,
        y 8888
      }
    },
    {
      delta node-XY5 : {
        x 2501,
        y 3909
      }
    },
    {
      delta node-XY4 : {
        x 1725,
        y 2920
      }
    }
  },
  {
    laneID 4,
    egressApproach 2,
    laneAttributes {
      directionalUse {egressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
      {
        delta node-XY4 : {
          x 1404,
          y 1669
        }
      },
      {
        delta node-XY3 : {
          x 970,
          y 1635
        }
      }
    }
  },

```

```

    {
      delta node-XY3 : {
        x 715,
        y 1260
      }
    },
    {
      delta node-XY1 : {
        x 361,
        y 133
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 3,
        maneuver {maneuverStraightAllowed}
      }
    }
  }
},
{
  laneID 5,
  ingressApproach 3,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed, maneuverRightAllowed,
    maneuverRightTurnOnRedAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x 2037,
        y 188
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 782
            }
          }
        }
      },
      dWidth 30
    }
  },
  {
    delta node-XY6 : {
      x 8360,
      y -5204
    }
  },
  {
    delta node-XY5 : {
      x 5862,
      y -3640
    }
  },
  {
    delta node-XY6 : {
      x 8931,
      y -5590
    }
  }
}

```

```

    }
  },
  connectsTo {
    {
      connectingLane {
        lane 3,
        maneuver {maneuverRightAllowed}
      },
      signalGroup 6
    },
    {
      connectingLane {
        lane 22,
        maneuver {maneuverStraightAllowed}
      },
      signalGroup 6
    }
  },
  {
    laneID 6,
    ingressApproach 3,
    laneAttributes {
      directionalUse {ingressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
      {
        delta node-XY3 : {
          x 1886,
          y -176
        }
      },
      {
        delta node-XY6 : {
          x 8387,
          y -5169
        }
      },
      {
        delta node-XY5 : {
          x 5678,
          y -3568
        }
      },
      {
        delta node-XY6 : {
          x 9038,
          y -5602
        }
      }
    },
    connectsTo {
      {
        connectingLane {
          lane 23,
          maneuver {maneuverStraightAllowed}
        },
        signalGroup 6
      }
    }
  },
  {

```

```

laneID 7,
ingressApproach 3,
laneAttributes {
  directionalUse {ingressPath},
  sharedWith {},
  laneType vehicle : {}
},
maneuvers {maneuverStraightAllowed},
nodeList nodes : {
  {
    delta node-XY3 : {
      x 1737,
      y -442
    }
  },
  {
    delta node-XY6 : {
      x 8064,
      y -5054
    }
  },
  {
    delta node-XY5 : {
      x 5961,
      y -3712
    }
  },
  {
    delta node-XY6 : {
      x 9038,
      y -5575
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 8,
      maneuver {maneuverStraightAllowed}
    }
  },
  {
    connectingLane {
      lane 24,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 6
  }
}
},
{
laneID 8,
ingressApproach 3,
laneAttributes {
  directionalUse {ingressPath},
  sharedWith {},
  laneType vehicle : {}
},
maneuvers {maneuverLeftAllowed, maneuverUTurnAllowed},
nodeList nodes : {
  {
    delta node-XY3 : {
      x 1618,
      y -774
    },
    attributes {

```

```

        dWidth -30
    }
},
{
    delta node-XY5 : {
        x 4404,
        y -2779
    }
},
{
    delta node-XY4 : {
        x 2964,
        y -1897
    }
},
{
    delta node-XY2 : {
        x 815,
        y -46
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 16,
            maneuver {maneuverLeftAllowed}
        },
        signalGroup 1
    },
    {
        connectingLane {
            lane 12,
            maneuver {maneuverUTurnAllowed}
        },
        signalGroup 1
    }
}
},
{
    laneID 9,
    egressApproach 4,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x 1024,
                y -2944
            },
            attributes {
                dWidth 30
            }
        },
        {
            delta node-XY2 : {
                x 908,
                y 97
            }
        },
        {
            delta node-XY2 : {

```



```

        x 690,
        y -21
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 10,
            maneuver {maneuverStraightAllowed}
        }
    }
}
},
{
    laneID 10,
    egressApproach 4,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x 1143,
                y -1931
            }
        },
        {
            delta node-XY3 : {
                x 1479,
                y -937
            }
        },
        {
            delta node-XY5 : {
                x 6688,
                y -4216
            }
        },
        {
            delta node-XY5 : {
                x 5515,
                y -3320
            }
        },
        {
            delta node-XY6 : {
                x 9335,
                y -5906
            }
        }
    },
    connectsTo {
        {
            connectingLane {
                lane 34,
                maneuver {maneuverStraightAllowed}
            },
            remoteIntersection {
                region 0,
                id 1031
            }
        }
    }
}

```

```

    }
  },
  {
    laneID 11,
    egressApproach 4,
    laneAttributes {
      directionalUse {egressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
      {
        delta node-XY4 : {
          x 1265,
          y -1621
        }
      },
      {
        delta node-XY6 : {
          x 8320,
          y -5170
        }
      },
      {
        delta node-XY5 : {
          x 5364,
          y -3315
        }
      },
      {
        delta node-XY6 : {
          x 9395,
          y -5893
        }
      }
    },
    connectsTo {
      {
        connectingLane {
          lane 35,
          maneuver {maneuverStraightAllowed}
        },
        remoteIntersection {
          region 0,
          id 1031
        }
      }
    }
  },
  {
    laneID 12,
    egressApproach 4,
    laneAttributes {
      directionalUse {egressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
      {
        delta node-XY3 : {
          x 1397,
          y -1303
        }
      },
    },
  }
}

```

```

    {
      delta node-XY6 : {
        x 8222,
        y -5122
      }
    },
    {
      delta node-XY5 : {
        x 5564,
        y -3456
      }
    },
    {
      delta node-XY6 : {
        x 9266,
        y -5840
      }
    }
  },
connectsTo {
  {
    connectingLane {
      lane 36,
      maneuver {maneuverStraightAllowed}
    },
    remoteIntersection {
      region 0,
      id 1031
    }
  }
}
},
{
  laneID 13,
  ingressApproach 5,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverRightAllowed, maneuverRightTurnOnRedAllowed},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x 775,
        y -3186
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 559
            }
          }
        },
        dWidth -30
      }
    },
    {
      delta node-XY2 : {
        x -502,
        y -596
      }
    }
  },
}

```

```

    delta node-XY3 : {
      x -259,
      y -1014
    }
  },
  {
    delta node-XY3 : {
      x -127,
      y -1228
    }
  },
  {
    delta node-XY3 : {
      x -120,
      y -1829
    }
  },
  {
    delta node-XY4 : {
      x 45,
      y -3779
    }
  },
  {
    delta node-XY4 : {
      x -33,
      y -3119
    }
  },
  {
    delta node-XY5 : {
      x 27,
      y -7293
    }
  },
  {
    delta node-XY2 : {
      x -394,
      y -520
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 9,
      maneuver {maneuverRightAllowed}
    },
    signalGroup 3
  }
}
},
{
  laneID 14,
  ingressApproach 5,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x -81,
        y -2406
      }
    }
  }
}
}

```

```

    }
  },
  {
    delta node-XY3 : {
      x -381,
      y -1199
    }
  },
  {
    delta node-XY3 : {
      x -145,
      y -1454
    }
  },
  {
    delta node-XY4 : {
      x 12,
      y -2753
    }
  },
  {
    delta node-XY4 : {
      x 41,
      y -3753
    }
  },
  {
    delta node-XY4 : {
      x -39,
      y -3082
    }
  },
  {
    delta node-XY5 : {
      x 42,
      y -5146
    }
  },
  {
    delta node-XY4 : {
      x -37,
      y -2771
    }
  },
  {
    delta node-XY4 : {
      x -136,
      y -2060
    }
  },
  {
    delta node-XY6 : {
      x 39,
      y -12703
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 13,
      maneuver {maneuverStraightAllowed}
    }
  },
  {
    connectingLane {

```

```

        lane 15,
        maneuver {maneuverStraightAllowed}
    }
},
{
    connectingLane {
        lane 3,
        maneuver {maneuverStraightAllowed}
    },
    signalGroup 3
}
}
},
{
    laneID 15,
    ingressApproach 5,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverLeftAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x -383,
                y -2219
            }
        },
        {
            delta node-XY3 : {
                x -402,
                y -1040
            }
        },
        {
            delta node-XY3 : {
                x -99,
                y -1233
            }
        },
        {
            delta node-XY3 : {
                x -31,
                y -2021
            }
        },
        {
            delta node-XY5 : {
                x 79,
                y -4862
            }
        },
        {
            delta node-XY1 : {
                x 282,
                y -190
            }
        }
    },
    connectsTo {
        {
            connectingLane {
                lane 24,
                maneuver {maneuverLeftAllowed}
            },

```

```

        signalGroup 3
    }
}
},
{
    laneID 16,
    egressApproach 6,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed, maneuverRightAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x -1180,
                y -1700
            }
        },
        {
            delta node-XY3 : {
                x -300,
                y -1411
            }
        },
        {
            delta node-XY3 : {
                x -143,
                y -1566
            }
        },
        {
            delta node-XY5 : {
                x 2,
                y -4391
            }
        },
        {
            delta node-XY5 : {
                x 35,
                y -5068
            }
        },
        {
            delta node-XY6 : {
                x -19,
                y -9740
            }
        },
        {
            delta node-XY5 : {
                x 35,
                y -7322
            }
        },
        {
            delta node-XY5 : {
                x -14,
                y -6033
            }
        }
    },
    connectsTo {
        {
            connectingLane {

```

```

        lane 17,
        maneuver {maneuverStraightAllowed}
    }
}
},
{
    laneID 17,
    egressApproach 6,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverLeftAllowed},
    nodeList nodes : {
        {
            delta node-XY6 : {
                x -1570,
                y -31198
            }
        },
        {
            delta node-XY2 : {
                x 432,
                y -556
            }
        },
        {
            delta node-XY5 : {
                x -12,
                y -5530
            }
        }
    }
},
{
    laneID 18,
    ingressApproach 7,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed, maneuverRightAllowed,
        maneuverRightTurnOnRedAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x -2054,
                y -44
            },
            attributes {
                data {
                    speedLimits : {
                        {
                            type vehicleMaxSpeed,
                            speed 782
                        }
                    }
                },
                dWidth 30
            }
        },
        {
            delta node-XY5 : {

```



```

        x -5027,
        y 3097
    }
},
{
    delta node-XY4 : {
        x -3070,
        y 1924
    }
},
{
    delta node-XY5 : {
        x -5818,
        y 3646
    }
},
{
    delta node-XY6 : {
        x -7830,
        y 4834
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 16,
            maneuver {maneuverRightAllowed}
        },
        signalGroup 2
    },
    {
        connectingLane {
            lane 10,
            maneuver {maneuverStraightAllowed}
        },
        signalGroup 2
    }
}
},
{
    laneID 19,
    ingressApproach 7,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x -1932,
                y 277
            }
        },
        {
            delta node-XY5 : {
                x -4915,
                y 3010
            }
        },
        {
            delta node-XY4 : {
                x -3105,
                y 1950
            }
        }
    }
}
}

```

```

    }
  },
  {
    delta node-XY5 : {
      x -6387,
      y 3983
    }
  },
  {
    delta node-XY6 : {
      x -7230,
      y 4434
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 11,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 2
  }
}
},
{
  laneID 20,
  ingressApproach 7,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1729,
        y 578
      }
    },
    {
      delta node-XY5 : {
        x -4670,
        y 2855
      }
    },
    {
      delta node-XY4 : {
        x -3246,
        y 2039
      }
    },
    {
      delta node-XY5 : {
        x -6636,
        y 4116
      }
    },
    {
      delta node-XY6 : {
        x -6977,
        y 4338
      }
    }
  }
},

```

```

connectsTo {
  {
    connectingLane {
      lane 12,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 2
  },
  {
    connectingLane {
      lane 21,
      maneuver {maneuverStraightAllowed}
    }
  }
},
{
  laneID 21,
  ingressApproach 7,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverLeftAllowed, maneuverUTurnAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1578,
        y 865
      },
      attributes {
        dWidth -30
      }
    },
    {
      delta node-XY5 : {
        x -4734,
        y 2948
      }
    },
    {
      delta node-XY4 : {
        x -2563,
        y 1626
      }
    },
    {
      delta node-XY2 : {
        x -770,
        y 33
      }
    }
  },
connectsTo {
  {
    connectingLane {
      lane 4,
      maneuver {maneuverLeftAllowed}
    },
    signalGroup 5
  },
  {
    connectingLane {
      lane 24,
      maneuver {maneuverUTurnAllowed}
    }
  }
}

```

```

    },
    signalGroup 5
  }
},
{
  laneID 22,
  egressApproach 8,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -673,
        y 1787
      },
      attributes {
        dWidth 30
      }
    },
    {
      delta node-XY6 : {
        x -8098,
        y 5014
      }
    },
    {
      delta node-XY4 : {
        x -2905,
        y 1856
      }
    },
    {
      delta node-XY5 : {
        x -3524,
        y 2194
      }
    },
    {
      delta node-XY5 : {
        x -6928,
        y 4357
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 8,
        maneuver {maneuverStraightAllowed}
      },
      remoteIntersection {
        region 0,
        id 1029
      }
    }
  }
},
{
  laneID 23,
  egressApproach 8,
  laneAttributes {

```

```

    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -943,
        y 1530
      }
    },
    {
      delta node-XY6 : {
        x -7865,
        y 4852
      }
    },
    {
      delta node-XY4 : {
        x -3140,
        y 2031
      }
    },
    {
      delta node-XY5 : {
        x -3511,
        y 2192
      }
    },
    {
      delta node-XY5 : {
        x -6822,
        y 4213
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 9,
        maneuver {maneuverStraightAllowed}
      },
      remoteIntersection {
        region 0,
        id 1029
      }
    }
  }
},
{
  laneID 24,
  egressApproach 8,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1188,
        y 1299
      }
    },
  },

```

```

    {
      delta node-XY6 : {
        x -7953,
        y 4935
      }
    },
    {
      delta node-XY4 : {
        x -3012,
        y 1895
      }
    },
    {
      delta node-XY5 : {
        x -3505,
        y 2195
      }
    },
    {
      delta node-XY5 : {
        x -6919,
        y 4312
      }
    }
  },
connectsTo {
  {
    connectingLane {
      lane 25,
      maneuver {maneuverStraightAllowed}
    }
  },
  {
    connectingLane {
      lane 10,
      maneuver {maneuverStraightAllowed}
    },
    remoteIntersection {
      region 0,
      id 1029
    }
  }
}
},
{
  laneID 25,
  egressApproach 8,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverUTurnAllowed},
  nodeList nodes : {
    {
      delta node-XY6 : {
        x -12153,
        y 8129
      }
    },
    {
      delta node-XY2 : {
        x -692,
        y -3
      }
    }
  },

```

```

    {
      delta node-XY4 : {
        x -3106,
        y 1925
      }
    },
    {
      delta node-XY5 : {
        x -5262,
        y 3275
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 20,
        maneuver {maneuverUTurnAllowed}
      }
    }
  },
  {
    laneID 26,
    laneAttributes {
      directionalUse {ingressPath, egressPath},
      sharedWith {},
      laneType crosswalk : {hasPushToWalkButton, audioSupport}
    },
    nodeList nodes : {
      {
        delta node-XY4 : {
          x 43,
          y 2474
        },
        attributes {
          dWidth -30
        }
      },
      {
        delta node-XY4 : {
          x 2199,
          y -1458
        }
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 27,
        maneuver {maneuverRightAllowed}
      },
      signalGroup 14
    },
    {
      connectingLane {
        lane 29,
        maneuver {maneuverLeftAllowed}
      },
      signalGroup 14
    }
  }
},
{
  laneID 27,
  laneAttributes {

```

```

    directionalUse {ingressPath, egressPath},
    sharedWith {},
    laneType crosswalk : {hasPushToWalkButton, audioSupport}
  },
  nodeList nodes : {
    {
      delta node-XY4 : {
        x 2242,
        y 1016
      }
    },
    {
      delta node-XY4 : {
        x -884,
        y -1998
      }
    },
    {
      delta node-XY3 : {
        x -749,
        y -1638
      }
    },
    {
      delta node-XY2 : {
        x 509,
        y -848
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 26,
        maneuver {maneuverLeftAllowed}
      },
      signalGroup 11
    },
    {
      connectingLane {
        lane 28,
        maneuver {maneuverRightAllowed}
      },
      signalGroup 11
    }
  }
},
{
  laneID 28,
  laneAttributes {
    directionalUse {ingressPath, egressPath},
    sharedWith {},
    laneType crosswalk : {}
  },
  nodeList nodes : {
    {
      delta node-XY4 : {
        x 1118,
        y -3468
      }
    },
    {
      delta node-XY2 : {
        x -509,
        y 848
      }
    }
  }
}

```



```

    },
    {
      delta node-XY3 : {
        x -1119,
        y 662
      }
    },
    {
      delta node-XY4 : {
        x -1850,
        y 1146
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 27,
        maneuver {maneuverLeftAllowed}
      },
      signalGroup 10
    },
    {
      connectingLane {
        lane 29,
        maneuver {maneuverRightAllowed}
      },
      signalGroup 10
    }
  }
},
{
  laneID 29,
  laneAttributes {
    directionalUse {ingressPath, egressPath},
    sharedWith {},
    laneType crosswalk : {}
  },
  nodeList nodes : {
    {
      delta node-XY4 : {
        x -2360,
        y -812
      }
    },
    {
      delta node-XY3 : {
        x 1063,
        y 1748
      }
    },
    {
      delta node-XY3 : {
        x 1340,
        y 1538
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 26,
        maneuver {maneuverRightAllowed}
      },
      signalGroup 12
    },
  },

```

```
{
  connectingLane {
    lane 28,
    maneuver {maneuverLeftAllowed}
  },
  signalGroup 12
}
}
}
}
}
}
}
```