

Intersection: Los Altos Ave at El Camino Real, Palo Alto, California

MapData payload size 917

```
payload=00128391280A3011000003F900A5F833BC9140080F885F014A192C0114000003900095783E0010140A22F1EE0
35A02C85C24161CD71924290001121B000089142000418022200000200009590DC3E18140A22F8787B92D760B1F3154
57EB5BE5806680000052001ABC55C2430281461D0F0F3EA50B1DF64F363C0C9BA478F03348A408800192290000C5808
680000040001AB7898A030281461D0F0F41C5211DF20F223C231BEC78DE3318245600018B014D0000008000356542B1
8605028C3A1E1E97C97E3BE29EE478423778F0EA6CB048B4000316031A000000A0002AB854B1080A051870F4D44B725
6489F08A4390000521420002380E840000040100ADA647760C0A0518743C1F48B785B4A77E010880018084200000200
00D4F003EC18140A30E87876FB40E92CC8489C76AB4658F0307721809420000020000D512A55618140A30E878957028
343C421BD476DC4440F0E06EF180A420000020000D53546CC18140A30E8787A8027B8F10C6A21DB990F43C801988B02
D5000000240015AF64DE618140A22F87825299108B2CC24120E400105818A80000060001A8ADC9EC20281445E349B9A
8CAD088C022568175F9C2AAC5A3130A40A0002122C80010381AC40000040100ACD9ECA40C0A05117C3C16CE24049182
04010E800180E620000020000D435E6BE10140A22F1A44CDAE568565F872B415AFDD1556E91C08B03DD000000240015
9B89C2E18140A30E8782CF3CE0D3258CB04869000116083A00000100006A1B67BC0C0A0518743C32FD6B0887A4E37E3
3F0E4BC68CDC330242200008B045D000000800035143C6B8605028C3A1E226DB6C511286BB986772C7E0D1758950484
C000116093A00000100006A375A010C0A0518743C44C86DD0225317200CF4B9581A3330B4090A800022C13740000014
0005489961810140A30E1A61AE0C34D9DAB452048000A916100051C1482000002000094EF9DA218140A30E87886D2E7
EE330DEAEC66A2D6B0440E002000007F0382B04000004000129A4370C30281461D0F10DDCCDB0657DDB28CD49AD7088
2400400000FE0705A08000008000252D5E648605028C3A1E21C2B9B00CA71B51199D35D61105800800001FC120BCB00
04180000719BC680B2A4B7C52304001C91A4000E2418A60008340010F02B0A110FE201889012683108440A45D000412
324002048336C0010680021B24CB8C177DDE0493F84210C0FE852308001491A2000A241AC60008340010CAA0D590FA0
80C2CA7DD616026CD8A45C8003123280018
```

gov.usdot.asn1.generated.j2735.dsrc.MessageFrame

```
value MessageFrame ::= {
  messageId 18,
  value MapData : {
    msgIssueRevision 10,
    layerType intersectionData,
    intersections {
      {
        id {
          region 0,
          id 1017
        },
        revision 0,
        refPoint {
          lat 374046329,
          long -1221181920,
          elevation 190
        },
        laneWidth 330,
        laneSet {
          {
            laneID 1,
            ingressApproach 1,
            laneAttributes {
              directionalUse {ingressPath},
              sharedWith {},
              laneType vehicle : {}
            },
            maneuvers {maneuverStraightAllowed, maneuverLeftAllowed, maneuverRightAllowed,
              maneuverRightTurnOnRedAllowed},
            nodeList nodes : {
              {
                delta node-XY3 : {
                  x 961,
                  y 1792
                },
                attributes {
                  data {
                    speedLimits : {
                      {
                        type vehicleMaxSpeed,
```

```

        speed 559
    }
}
},
{
    delta node-XY4 : {
        x 2944,
        y 2768
    }
},
{
    delta node-XY3 : {
        x 1157,
        y 1060
    }
},
{
    delta node-XY3 : {
        x 1081,
        y 739
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 10,
            maneuver {maneuverLeftAllowed}
        },
        signalGroup 4
    },
    {
        connectingLane {
            lane 13,
            maneuver {maneuverStraightAllowed}
        },
        signalGroup 4
    },
    {
        connectingLane {
            lane 20,
            maneuver {maneuverRightAllowed}
        },
        signalGroup 4
    }
}
},
{
    laneID 2,
    egressApproach 2,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x 1158,
                y 1567
            },
            attributes {
                data {

```

```

        speedLimits : {
            {
                type vehicleMaxSpeed,
                speed 559
            }
        },
        dWidth 30
    }
},
{
    delta node-XY4 : {
        x 2962,
        y 2796
    }
},
{
    delta node-XY3 : {
        x 1148,
        y 1109
    }
},
{
    delta node-XY3 : {
        x 1013,
        y 735
    }
}
},
{
    laneID 3,
    ingressApproach 3,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed, maneuverRightAllowed,
        maneuverRightTurnOnRedAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x 1813,
                y -247
            },
            attributes {
                data {
                    speedLimits : {
                        {
                            type vehicleMaxSpeed,
                            speed 782
                        }
                    }
                },
                dWidth 30
            }
        },
        {
            delta node-XY4 : {
                x 2549,
                y -2805
            }
        },
        {
            delta node-XY4 : {

```

```

        x 2009,
        y -2149
    }
},
{
    delta node-XY4 : {
        x 2073,
        y -2327
    }
},
{
    delta node-XY4 : {
        x 2288,
        y -2455
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 2,
            maneuver {maneuverRightAllowed}
        },
        signalGroup 6
    },
    {
        connectingLane {
            lane 20,
            maneuver {maneuverStraightAllowed}
        },
        signalGroup 6
    }
}
},
{
    laneID 4,
    ingressApproach 3,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x 1506,
                y -472
            },
            attributes {
                data {
                    speedLimits : {
                        {
                            type vehicleMaxSpeed,
                            speed 782
                        }
                    }
                }
            },
            dWidth 30
        }
    },
    {
        delta node-XY4 : {
            x 2574,
            y -2783
        }
    }
}
}

```

```

    },
    {
      delta node-XY4 : {
        x 1992,
        y -2159
      }
    },
    {
      delta node-XY4 : {
        x 2118,
        y -2309
      }
    },
    {
      delta node-XY4 : {
        x 2270,
        y -2461
      }
    }
  },
connectsTo {
  {
    connectingLane {
      lane 21,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 6
  }
}
},
{
  laneID 5,
  ingressApproach 3,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x 1192,
        y -669
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 782
            }
          }
        },
        dWidth 30
      }
    },
    {
      delta node-XY4 : {
        x 2655,
        y -2881
      }
    },
    {
      delta node-XY4 : {
        x 1989,

```

```

        y -2119
    }
},
{
    delta node-XY4 : {
        x 2114,
        y -2321
    }
},
{
    delta node-XY4 : {
        x 2165,
        y -2357
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 22,
            maneuver {maneuverStraightAllowed}
        },
        signalGroup 6
    }
}
},
{
    laneID 6,
    ingressApproach 3,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverLeftAllowed, maneuverUTurnAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x 901,
                y -847
            },
            attributes {
                data {
                    speedLimits : {
                        {
                            type vehicleMaxSpeed,
                            speed 782
                        }
                    }
                }
            }
        },
        {
            delta node-XY4 : {
                x 2666,
                y -2889
            }
        },
        {
            delta node-XY5 : {
                x 2852,
                y -3103
            }
        }
    }
},
connectsTo {

```

```

    {
      connectingLane {
        lane 14,
        maneuver {maneuverLeftAllowed}
      },
      signalGroup 1
    },
    {
      connectingLane {
        lane 10,
        maneuver {maneuverUTurnAllowed}
      },
      signalGroup 1
    }
  },
  {
    laneID 7,
    egressApproach 4,
    laneAttributes {
      directionalUse {egressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed, caution},
    nodeList nodes : {
      {
        delta node-XY4 : {
          x -718,
          y -2186
        },
        attributes {
          data {
            speedLimits : {
              {
                type vehicleMaxSpeed,
                speed 782
              }
            }
          },
          dWidth 30
        }
      },
      {
        delta node-XY2 : {
          x 932,
          y -290
        }
      },
      {
        delta node-XY3 : {
          x 1445,
          y -1089
        }
      }
    },
    connectsTo {
      {
        connectingLane {
          lane 8,
          maneuver {maneuverStraightAllowed}
        }
      }
    }
  },
  {

```

```

laneID 8,
egressApproach 4,
laneAttributes {
  directionalUse {egressPath},
  sharedWith {},
  laneType vehicle : {}
},
maneuvers {maneuverStraightAllowed},
nodeList nodes : {
  {
    delta node-XY3 : {
      x -128,
      y -1546
    },
    attributes {
      data {
        speedLimits : {
          {
            type vehicleMaxSpeed,
            speed 782
          }
        }
      },
      dWidth 30
    }
  },
  {
    delta node-XY4 : {
      x 1787,
      y -2019
    }
  },
  {
    delta node-XY5 : {
      x 3272,
      y -3545
    }
  },
  {
    delta node-XY4 : {
      x 1707,
      y -1845
    }
  },
  {
    delta node-XY4 : {
      x 2072,
      y -2190
    }
  }
},
{
  laneID 9,
  egressApproach 4,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x 149,
        y -1365
      }
    }
  }
}

```



```

    },
    attributes {
      data {
        speedLimits : {
          {
            type vehicleMaxSpeed,
            speed 782
          }
        }
      },
      dWidth 30
    }
  },
  {
    delta node-XY5 : {
      x 2784,
      y -3046
    }
  },
  {
    delta node-XY4 : {
      x 2180,
      y -2315
    }
  },
  {
    delta node-XY4 : {
      x 1756,
      y -1912
    }
  },
  {
    delta node-XY4 : {
      x 2160,
      y -2321
    }
  }
},
{
  laneID 10,
  egressApproach 4,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x 426,
        y -1178
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 782
            }
          }
        },
        dWidth 30
      }
    }
  },

```

```

    {
      delta node-XY4 : {
        x 2688,
        y -2825
      }
    },
    {
      delta node-XY4 : {
        x 2182,
        y -2398
      }
    },
    {
      delta node-XY4 : {
        x 1766,
        y -1926
      }
    },
    {
      delta node-XY4 : {
        x 2304,
        y -2462
      }
    }
  },
  {
    laneID 11,
    ingressApproach 5,
    laneAttributes {
      directionalUse {ingressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverRightAllowed, maneuverRightTurnOnRedAllowed},
    nodeList nodes : {
      {
        delta node-XY4 : {
          x -1063,
          y -2317
        },
        attributes {
          data {
            speedLimits : {
              {
                type vehicleMaxSpeed,
                speed 559
              }
            }
          },
          dWidth 30
        }
      },
      {
        delta node-XY2 : {
          x -694,
          y -222
        }
      },
      {
        delta node-XY3 : {
          x -1333,
          y -1271
        }
      }
    }
  },

```

```

connectsTo {
  {
    connectingLane {
      lane 7,
      maneuver {maneuverRightAllowed}
    },
    signalGroup 8
  }
},
{
  laneID 12,
  ingressApproach 5,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed, maneuverLeftAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1353,
        y -1413
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 559
            }
          }
        }
      }
    },
    {
      delta node-XY4 : {
        x -1737,
        y -2397
      }
    },
    {
      delta node-XY6 : {
        x -6076,
        y -8175
      }
    },
    {
      delta node-XY6 : {
        x -6121,
        y -8292
      }
    },
    {
      delta node-XY6 : {
        x -10869,
        y -14810
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 2,
        maneuver {maneuverStraightAllowed}
      }
    }
  }
}

```

```

    },
    signalGroup 8
  },
  {
    connectingLane {
      lane 22,
      maneuver {maneuverLeftAllowed}
    },
    signalGroup 8
  }
}
},
{
  laneID 13,
  egressApproach 6,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed, caution},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x -2353,
        y -860
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 559
            }
          }
        },
        dWidth 30
      }
    },
    {
      delta node-XY2 : {
        x -153,
        y -880
      }
    },
    {
      delta node-XY3 : {
        x -884,
        y -1790
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 14,
        maneuver {maneuverStraightAllowed}
      }
    }
  }
},
{
  laneID 14,
  egressApproach 6,
  laneAttributes {
    directionalUse {egressPath},

```

```

    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1617,
        y -1185
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 559
            }
          }
        }
      }
    },
    {
      delta node-XY4 : {
        x -1773,
        y -2345
      }
    },
    {
      delta node-XY6 : {
        x -6058,
        y -8313
      }
    },
    {
      delta node-XY6 : {
        x -6101,
        y -8262
      }
    },
    {
      delta node-XY6 : {
        x -10822,
        y -14590
      }
    }
  },
  {
    laneID 15,
    ingressApproach 7,
    laneAttributes {
      directionalUse {ingressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverRightAllowed, maneuverRightTurnOnRedAllowed},
    nodeList nodes : {
      {
        delta node-XY4 : {
          x -2334,
          y -489
        },
        attributes {
          data {
            speedLimits : {
              {

```

```

                type vehicleMaxSpeed,
                speed 782
            }
        },
        dWidth 30
    }
},
{
    delta node-XY2 : {
        x -196,
        y 924
    }
},
{
    delta node-XY4 : {
        x -1646,
        y 2251
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 13,
            maneuver {maneuverRightAllowed}
        },
        signalGroup 2
    }
}
},
{
    laneID 16,
    ingressApproach 7,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x -1610,
                y -68
            },
            attributes {
                data {
                    speedLimits : {
                        {
                            type vehicleMaxSpeed,
                            speed 782
                        }
                    }
                },
                dWidth 30
            }
        },
        {
            delta node-XY4 : {
                x -2566,
                y 2754
            }
        },
        {
            delta node-XY5 : {

```

```

        x -4279,
        y 4543
    }
},
{
    delta node-XY4 : {
        x -2079,
        y 2351
    }
},
{
    delta node-XY4 : {
        x -1843,
        y 2150
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 8,
            maneuver {maneuverStraightAllowed}
        },
        signalGroup 2
    }
}
},
{
    laneID 17,
    ingressApproach 7,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x -1401,
                y 215
            },
            attributes {
                data {
                    speedLimits : {
                        {
                            type vehicleMaxSpeed,
                            speed 782
                        }
                    }
                }
            },
            dWidth 30
        }
    },
    {
        delta node-XY5 : {
            x -3219,
            y 3466
        }
    },
    {
        delta node-XY5 : {
            x -3450,
            y 3814
        }
    }
},

```

```

    {
      delta node-XY4 : {
        x -2190,
        y 2300
      }
    },
    {
      delta node-XY4 : {
        x -1862,
        y 2197
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 9,
        maneuver {maneuverStraightAllowed}
      },
      signalGroup 2
    }
  }
},
{
  laneID 18,
  ingressApproach 7,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1163,
        y 513
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 782
            }
          }
        }
      },
      dWidth 30
    }
  },
  {
    delta node-XY5 : {
      x -3295,
      y 3536
    }
  },
  {
    delta node-XY5 : {
      x -3432,
      y 3648
    }
  },
  {
    delta node-XY4 : {
      x -2139,
      y 2392
    }
  }
}

```



```

    }
  },
  {
    delta node-XY4 : {
      x -1844,
      y 2138
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 10,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 2
  }
}
},
{
  laneID 19,
  ingressApproach 7,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverLeftAllowed, maneuverUTurnAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -948,
        y 780
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 782
            }
          }
        }
      }
    }
  },
  {
    delta node-XY4 : {
      x -1658,
      y 1798
    }
  },
  {
    delta node-XY4 : {
      x -1613,
      y 1709
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 2,
      maneuver {maneuverLeftAllowed}
    },
    signalGroup 5
  },

```

```

    {
      connectingLane {
        lane 22,
        maneuver {maneuverUTurnAllowed}
      },
      signalGroup 5
    }
  },
  {
    laneID 20,
    egressApproach 8,
    laneAttributes {
      directionalUse {egressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
      {
        delta node-XY3 : {
          x -132,
          y 1745
        },
        attributes {
          data {
            speedLimits : {
              {
                type vehicleMaxSpeed,
                speed 782
              }
            }
          },
          dWidth 30
        }
      },
      {
        delta node-XY5 : {
          x -4699,
          y 5111
        }
      },
      {
        delta node-XY4 : {
          x -2533,
          y 2747
        }
      },
      {
        delta node-XY4 : {
          x -2398,
          y 2774
        }
      }
    },
    connectsTo {
      {
        connectingLane {
          lane 3,
          maneuver {maneuverStraightAllowed}
        },
        remoteIntersection {
          region 0,
          id 1016
        }
      }
    }
  }
}

```

```

    }
  },
  {
    laneID 21,
    egressApproach 8,
    laneAttributes {
      directionalUse {egressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
      {
        delta node-XY3 : {
          x -368,
          y 1475
        },
        attributes {
          data {
            speedLimits : {
              {
                type vehicleMaxSpeed,
                speed 782
              }
            }
          },
          dWidth 30
        }
      },
      {
        delta node-XY5 : {
          x -4644,
          y 4972
        }
      },
      {
        delta node-XY4 : {
          x -2691,
          y 2917
        }
      },
      {
        delta node-XY4 : {
          x -2396,
          y 2775
        }
      }
    },
    connectsTo {
      {
        connectingLane {
          lane 4,
          maneuver {maneuverStraightAllowed}
        },
        remoteIntersection {
          region 0,
          id 1016
        }
      }
    }
  },
  {
    laneID 22,
    egressApproach 8,
    laneAttributes {
      directionalUse {egressPath},

```

```

    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -597,
        y 1225
      },
      attributes {
        data {
          speedLimits : {
            {
              type vehicleMaxSpeed,
              speed 782
            }
          },
          dWidth 30
        }
      },
    },
    {
      delta node-XY5 : {
        x -4587,
        y 4960
      },
    },
    {
      delta node-XY4 : {
        x -2760,
        y 2897
      },
    },
    {
      delta node-XY4 : {
        x -2444,
        y 2795
      },
    },
  },
  connectsTo {
    {
      connectingLane {
        lane 5,
        maneuver {maneuverStraightAllowed}
      },
      remoteIntersection {
        region 0,
        id 1016
      }
    }
  },
  {
    laneID 23,
    ingressApproach 9,
    laneAttributes {
      directionalUse {ingressPath, egressPath},
      sharedWith {},
      laneType crosswalk : {hasPushToWalkButton, audioSupport}
    },
    nodeList nodes : {
      {
        delta node-XY4 : {
          x 411,

```

```

        y 2256
    }
},
{
    delta node-XY3 : {
        x 1193,
        y -1313
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 24,
            maneuver {maneuverRightAllowed}
        },
        signalGroup 14
    },
    {
        connectingLane {
            lane 26,
            maneuver {maneuverLeftAllowed}
        },
        signalGroup 14
    }
}
},
{
    laneID 24,
    ingressApproach 10,
    laneAttributes {
        directionalUse {ingressPath, egressPath},
        sharedWith {},
        laneType crosswalk : {hasPushToWalkButton, audioSupport,
            unsignalizedSegmentsPresent}
    },
    nodeList nodes : {
        {
            delta node-XY4 : {
                x 2069,
                y 161
            }
        },
        {
            delta node-XY3 : {
                x -1540,
                y -1021
            }
        },
        {
            delta node-XY3 : {
                x -1472,
                y -870
            }
        },
        {
            delta node-XY2 : {
                x 66,
                y -888
            }
        }
    },
    connectsTo {
        {
            connectingLane {
                lane 23,

```

```

        maneuver {maneuverLeftAllowed}
    },
    signalGroup 16
},
{
    connectingLane {
        lane 25,
        maneuver {maneuverRightAllowed}
    },
    signalGroup 16
}
}
},
{
    laneID 25,
    ingressApproach 11,
    laneAttributes {
        directionalUse {ingressPath, egressPath},
        sharedWith {},
        laneType crosswalk : {hasPushToWalkButton, audioSupport,
            unsignalizedSegmentsPresent}
    },
    nodeList nodes : {
        {
            delta node-XY4 : {
                x -877,
                y -2618
            }
        },
        {
            delta node-XY2 : {
                x -66,
                y 888
            }
        },
        {
            delta node-XY3 : {
                x -865,
                y 1057
            }
        },
        {
            delta node-XY2 : {
                x -928,
                y -6
            }
        }
    },
    connectsTo {
        {
            connectingLane {
                lane 24,
                maneuver {maneuverLeftAllowed}
            },
            signalGroup 10
        },
        {
            connectingLane {
                lane 26,
                maneuver {maneuverRightAllowed}
            },
            signalGroup 10
        }
    }
},
{

```

