

Intersection: Showers Dr at El Camino Real, Mountain View, California

MapData payload size 994

```
payload=001283DE280B3019000003FC00A5F7CC549140A7E7086E014A028C3870B00450000002400A1CAD30683BF3688
8782ACAA13555DEA4775DC0D12D90BB9476A4BD30EF539CB25AC78A812B18BDA895D25F184B81723C048C1000216010
A00000180014B9D25DF0121E1DF473FC3C4666C09A75EE763BB7613096905D623B775F4C77AFCCF12D60C690958CDE3
84ADEEF8525C0F90B1840E00020900091280004486A000216018A000000A00043A565B78778ACD68ECE176B0D5BE682
90E400044830800216020A000000200025B116B9CF257C16A6064264700830800C0291000000400163B45D5987785CD
A0ED837D42CB8D4CC89338DD6F0785BCD78EFD19D62596387112C12BF8C75BEB688ECFB7CB1E50F6E42B4EA451C0622
0000020002475ACAF28EEBD9C61DB66F725971599BC2666FAAE8F1219D91DFC73AE4B29F0B326041B0C0EDE596125A0
F8530041E000601C88000004000231140E4974BF00CDD0C23C563B025F749699626258106800000520008F1AAFF91E5
214D84CDF952D148290003246200018B024D000000800011DFC1D763CABAAC899902A640919800062C0A34000002000
085E94B5A3CBD290C779E5CF0F6769FC148D40003042E000B02CD00000050001574B242023C44B93D75D0F7D75A2912
40001487080008E062100000100002BA042098121E1F05D1CE4C2D16C10886400400000FF470350800000800011D321
28E3DF424A4984E2D94110D800800001FE8E0721000001000022D7A2A01EF452204C37169F0887400400000FF4B03D5
000000240035BE80F6808F1055D8E2136C9B405678330A20290290C2000308840016082A0000010000426790630AC01
EE16F04D0320CB80241A0000C60458800000800011A8B0E92240489521E6D48B0E093100000100004238C2120AA026E
16DE5C4359CDD884460002270003026C40000040002091FC5DC4CFE7C6180846C30D4A085BB9270A4222C5828E80000
052001283D5C70121E223F548B9564D668F49760ABD429122000248640001160ABA0000010000421A184F222214E110
918BD7488A2D3D4090D800022C16740000020000844B93044440E9E22129B78E11125A8A0521D000041178002C17740
0000140009465F51608F111079A8AC86245AB811791B8520C8000A91A100051C1882000002000094B6FD08090F10CB7
B3C08519DD1431FB64EC2215001000003FB1C1982000002000084A29AD243336CD32123B7AB0CA558540885C0040000
0FEC706A080000080002122EE3090CF2B22484A7DE8C323B623C2219001000003FB041B60008300002E0E58B1047887
8A75498247100038107180020C0002344B32F45751C4A2B51DCC048D90006000EB0004000000B4F0D6C603BBAA60C0
```

gov.usdot.asn1.generated.j2735.dsrc.MessageFrame

```
value MessageFrame ::= {
  messageId 18,
  value MapData : {
    msgIssueRevision 11,
    layerType intersectionData,
    intersections {
      {
        id {
          region 0,
          id 1020
        },
        revision 0,
        refPoint {
          lat 373993385,
          long -1221100081,
          elevation 220
        },
        laneWidth 330,
        speedLimits {
          {
            type vehicleMaxSpeed,
            speed 782
          }
        },
        laneSet {
          {
            laneID 1,
            ingressApproach 1,
            laneAttributes {
              directionalUse {ingressPath},
              sharedWith {},
              laneType vehicle : {}
            },
            maneuvers {maneuverRightAllowed, maneuverRightTurnOnRedAllowed},
            nodeList nodes : {
              {
                delta node-XY4 : {
                  x 692,
                  y 2100
                }
              }
            }
          }
        }
      }
    }
  }
}
```

```
    }
  },
  {
    delta node-XY4 : {
      x 2022,
      y 2594
    }
  },
  {
    delta node-XY4 : {
      x 2090,
      y 2388
    }
  },
  {
    delta node-XY5 : {
      x 5461,
      y 6057
    }
  },
  {
    delta node-XY4 : {
      x 1885,
      y 2074
    }
  },
  {
    delta node-XY5 : {
      x 3472,
      y 3813
    }
  },
  {
    delta node-XY4 : {
      x 1700,
      y 1958
    }
  },
  {
    delta node-XY4 : {
      x 1961,
      y 2507
    }
  },
  {
    delta node-XY5 : {
      x 3427,
      y 4432
    }
  },
  {
    delta node-XY5 : {
      x 2840,
      y 3946
    }
  },
  {
    delta node-XY5 : {
      x 2980,
      y 3980
    }
  },
  {
    delta node-XY5 : {
      x 3589,
      y 4668
    }
  }
}
```

```

    }
  },
  connectsTo {
    {
      connectingLane {
        lane 24,
        maneuver {maneuverRightAllowed}
      },
      signalGroup 4
    }
  },
  {
    laneID 2,
    ingressApproach 1,
    laneAttributes {
      directionalUse {ingressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed, maneuverLeftAllowed},
    nodeList nodes : {
      {
        delta node-XY4 : {
          x 932,
          y 1916
        },
        attributes {
          dWidth 30
        }
      },
      {
        delta node-XY4 : {
          x 2001,
          y 2558
        }
      },
      {
        delta node-XY4 : {
          x 2188,
          y 2480
        }
      },
      {
        delta node-XY5 : {
          x 5355,
          y 5947
        }
      },
      {
        delta node-XY4 : {
          x 1902,
          y 2124
        }
      },
      {
        delta node-XY5 : {
          x 3360,
          y 3761
        }
      },
      {
        delta node-XY4 : {
          x 1774,
          y 2003
        }
      }
    }
  }
}

```

```

    }
  },
  {
    delta node-XY4 : {
      x 1967,
      y 2462
    }
  },
  {
    delta node-XY5 : {
      x 3424,
      y 4516
    }
  },
  {
    delta node-XY5 : {
      x 2841,
      y 3868
    }
  },
  {
    delta node-XY5 : {
      x 2939,
      y 3973
    }
  },
  {
    delta node-XY5 : {
      x 3591,
      y 4630
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 3,
      maneuver {maneuverStraightAllowed}
    }
  },
  {
    connectingLane {
      lane 4,
      maneuver {maneuverStraightAllowed}
    }
  },
  {
    connectingLane {
      lane 18,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 4
  },
  {
    connectingLane {
      lane 13,
      maneuver {maneuverLeftAllowed}
    },
    signalGroup 4
  }
}
},
{
  laneID 3,
  ingressApproach 1,
  laneAttributes {

```

```

    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverLeftAllowed, maneuverUTurnAllowed},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x 1196,
        y 1758
      }
    },
    {
      delta node-XY4 : {
        x 1930,
        y 2477
      }
    },
    {
      delta node-XY4 : {
        x 1648,
        y 1899
      }
    },
    {
      delta node-XY2 : {
        x 347,
        y 820
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 14,
        maneuver {maneuverLeftAllowed}
      },
      signalGroup 4
    },
    {
      connectingLane {
        lane 6,
        maneuver {maneuverUTurnAllowed}
      },
      signalGroup 4
    }
  },
  {
    laneID 4,
    ingressApproach 1,
    laneAttributes {
      directionalUse {ingressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverUTurnAllowed},
    nodeList nodes : {
      {
        delta node-XY6 : {
          x 12566,
          y 14799
        }
      },
      {
        delta node-XY5 : {

```

```

        x 3040,
        y 3404
    }
},
{
    delta node-XY2 : {
        x 132,
        y 583
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 6,
            maneuver {maneuverUTurnAllowed}
        }
    }
}
},
{
    laneID 5,
    egressApproach 2,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverRightAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x 1675,
                y 1382
            }
        },
        {
            delta node-XY4 : {
                x 1925,
                y 2484
            }
        },
        {
            delta node-XY4 : {
                x 1729,
                y 2004
            }
        },
        {
            delta node-XY6 : {
                x 5914,
                y 6545
            }
        },
        {
            delta node-XY5 : {
                x 5005,
                y 5564
            }
        },
        {
            delta node-XY4 : {
                x 2139,
                y 2479
            }
        }
    }
},

```

```

    {
      delta node-XY4 : {
        x 2024,
        y 2518
      }
    },
    {
      delta node-XY5 : {
        x 3249,
        y 4322
      }
    },
    {
      delta node-XY5 : {
        x 3090,
        y 4067
      }
    },
    {
      delta node-XY4 : {
        x 1470,
        y 1745
      }
    },
    {
      delta node-XY4 : {
        x 1661,
        y 1995
      }
    },
    {
      delta node-XY4 : {
        x 2371,
        y 2930
      }
    },
    {
      delta node-XY3 : {
        x 846,
        y 581
      }
    }
  },
  {
    laneID 6,
    egressApproach 2,
    laneAttributes {
      directionalUse {egressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
      {
        delta node-XY4 : {
          x 1452,
          y 1509
        }
      },
      {
        delta node-XY4 : {
          x 1886,
          y 2502
        }
      }
    }
  },

```

```

    {
      delta node-XY4 : {
        x 1753,
        y 1977
      }
    },
    {
      delta node-XY6 : {
        x 5909,
        y 6588
      }
    },
    {
      delta node-XY5 : {
        x 4919,
        y 5469
      }
    },
    {
      delta node-XY4 : {
        x 2192,
        y 2521
      }
    },
    {
      delta node-XY4 : {
        x 2033,
        y 2519
      }
    },
    {
      delta node-XY5 : {
        x 3239,
        y 4275
      }
    },
    {
      delta node-XY5 : {
        x 4128,
        y 5656
      }
    },
    {
      delta node-XY4 : {
        x 1778,
        y 2401
      }
    },
    {
      delta node-XY5 : {
        x 3335,
        y 4262
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 7,
        maneuver {maneuverStraightAllowed}
      }
    }
  }
},
{
  laneID 7,

```



```

egressApproach 2,
laneAttributes {
  directionalUse {egressPath},
  sharedWith {},
  laneType vehicle : {}
},
maneuvers {maneuverLeftAllowed},
nodeList nodes : {
  {
    delta node-LatLon : {
      lon -1221069009,
      lat 374023133
    }
  },
  {
    delta node-XY2 : {
      x 35,
      y 555
    }
  },
  {
    delta node-XY4 : {
      x 1540,
      y 2013
    }
  },
  {
    delta node-XY5 : {
      x 3378,
      y 4401
    }
  }
}
},
{
  laneID 8,
  ingressApproach 3,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed, maneuverRightAllowed,
    maneuverRightTurnOnRedAllowed},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x 2261,
        y -7
      }
    },
    {
      delta node-XY4 : {
        x 2376,
        y -1428
      }
    },
    {
      delta node-XY5 : {
        x 4990,
        y -2771
      }
    }
  }
},
connectsTo {
  {

```

```

        connectingLane {
            lane 5,
            maneuver {maneuverRightAllowed}
        },
        signalGroup 6
    },
    {
        connectingLane {
            lane 24,
            maneuver {maneuverStraightAllowed}
        },
        signalGroup 6
    }
}
},
{
    laneID 9,
    ingressApproach 3,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x 2032,
                y -325
            }
        },
        {
            delta node-XY4 : {
                x 2391,
                y -1358
            }
        },
        {
            delta node-XY5 : {
                x 4896,
                y -2766
            }
        }
    },
    connectsTo {
        {
            connectingLane {
                lane 25,
                maneuver {maneuverStraightAllowed}
            },
            signalGroup 6
        }
    }
},
{
    laneID 10,
    ingressApproach 3,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {

```

```

        x 1866,
        y -595
    }
},
{
    delta node-XY4 : {
        x 2426,
        y -1469
    }
},
{
    delta node-XY4 : {
        x 1950,
        y -1122
    }
},
{
    delta node-XY4 : {
        x 2875,
        y -1540
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 26,
            maneuver {maneuverStraightAllowed}
        },
        signalGroup 6
    },
    {
        connectingLane {
            lane 11,
            maneuver {maneuverStraightAllowed}
        }
    }
}
},
{
    laneID 11,
    ingressApproach 3,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverLeftAllowed, maneuverUTurnAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x 1686,
                y -892
            },
            attributes {
                dWidth -30
            }
        },
        {
            delta node-XY5 : {
                x 3663,
                y -2211
            }
        },
        {
            delta node-XY2 : {

```

```

        x 893,
        y -83
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 18,
            maneuver {maneuverLeftAllowed}
        },
        signalGroup 1
    },
    {
        connectingLane {
            lane 14,
            maneuver {maneuverUTurnAllowed}
        },
        signalGroup 1
    }
}
},
{
    laneID 12,
    egressApproach 4,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY4 : {
                x 1032,
                y -2010
            },
            attributes {
                dWidth 30
            }
        },
        {
            delta node-XY4 : {
                x 3095,
                y -1817
            }
        },
        {
            delta node-XY5 : {
                x 4276,
                y -2367
            }
        }
    },
    connectsTo {
        {
            connectingLane {
                lane 12,
                maneuver {maneuverStraightAllowed}
            },
            remoteIntersection {
                region 0,
                id 1021
            }
        }
    }
}
}

```

```

},
{
  laneID 13,
  egressApproach 4,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x 1224,
        y -1721
      }
    },
    {
      delta node-XY4 : {
        x 3048,
        y -1751
      }
    },
    {
      delta node-XY5 : {
        x 4252,
        y -2358
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 13,
        maneuver {maneuverStraightAllowed}
      },
      remoteIntersection {
        region 0,
        id 1021
      }
    }
  }
},
{
  laneID 14,
  egressApproach 4,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x 1402,
        y -1376
      }
    },
    {
      delta node-XY4 : {
        x 3025,
        y -1776
      }
    }
  },
  {

```

```

    delta node-XY5 : {
      x 4316,
      y -2401
    }
  },
connectsTo {
  {
    connectingLane {
      lane 14,
      maneuver {maneuverStraightAllowed}
    },
    remoteIntersection {
      region 0,
      id 1021
    }
  }
},
{
  laneID 15,
  ingressApproach 5,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverRightAllowed, maneuverRightTurnOnRedAllowed},
  nodeList nodes : {
    {
      delta node-XY4 : {
        x -96,
        y -2124
      },
      attributes {
        dWidth -30
      }
    },
    {
      delta node-XY2 : {
        x -325,
        y -798
      }
    },
    {
      delta node-XY3 : {
        x -295,
        y -1176
      }
    },
    {
      delta node-XY2 : {
        x -305,
        y -973
      }
    },
    {
      delta node-XY2 : {
        x -480,
        y -696
      }
    }
  },
connectsTo {
  {
    connectingLane {

```

```

        lane 12,
        maneuver {maneuverRightAllowed}
    },
    signalGroup 3
},
{
    connectingLane {
        lane 16,
        maneuver {maneuverStraightAllowed}
    }
}
},
{
    laneID 16,
    ingressApproach 5,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x -391,
                y -1949
            }
        },
        {
            delta node-XY2 : {
                x -320,
                y -777
            }
        },
        {
            delta node-XY2 : {
                x -136,
                y -716
            }
        },
        {
            delta node-XY2 : {
                x 131,
                y -656
            }
        }
    },
    connectsTo {
        {
            connectingLane {
                lane 6,
                maneuver {maneuverStraightAllowed}
            },
            signalGroup 3
        }
    }
},
{
    laneID 17,
    egressApproach 6,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
},

```

```

maneuvers {maneuverStraightAllowed},
nodeList nodes : {
  {
    delta node-XY4 : {
      x -1492,
      y -2231
    }
  },
  {
    delta node-XY3 : {
      x -1020,
      y 149
    }
  },
  {
    delta node-XY5 : {
      x -4298,
      y 2326
    }
  }
},
{
  laneID 18,
  egressApproach 6,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1140,
        y -1518
      }
    },
    {
      delta node-XY2 : {
        x -352,
        y -713
      }
    },
    {
      delta node-XY2 : {
        x -145,
        y -655
      }
    },
    {
      delta node-XY2 : {
        x 359,
        y -581
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 17,
        maneuver {maneuverStraightAllowed}
      }
    },
    {
      connectingLane {

```



```

        lane 19,
        maneuver {maneuverStraightAllowed}
    }
}
},
{
    laneID 19,
    egressApproach 6,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x -897,
                y -1673
            }
        },
        {
            delta node-XY3 : {
                x -385,
                y -1053
            }
        },
        {
            delta node-XY2 : {
                x 4,
                y -741
            }
        },
        {
            delta node-XY2 : {
                x 53,
                y -703
            }
        },
        {
            delta node-XY2 : {
                x -137,
                y -729
            }
        },
        {
            delta node-XY2 : {
                x -446,
                y -746
            }
        }
    }
},
{
    laneID 20,
    ingressApproach 7,
    laneAttributes {
        directionalUse {ingressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed, maneuverRightAllowed,
        maneuverRightTurnOnRedAllowed},
    nodeList nodes : {
        {

```

```

    delta node-XY3 : {
      x -1803,
      y -228
    },
    attributes {
      dWidth 30
    }
  },
  {
    delta node-XY5 : {
      x -3590,
      y 2327
    }
  },
  {
    delta node-XY6 : {
      x -9931,
      y 6717
    }
  },
  {
    delta node-XY5 : {
      x 3777,
      y -2582
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 18,
      maneuver {maneuverRightAllowed}
    },
    signalGroup 2
  },
  {
    connectingLane {
      lane 12,
      maneuver {maneuverStraightAllowed}
    },
    signalGroup 2
  }
}
},
{
  laneID 21,
  ingressApproach 7,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1631,
        y 79
      }
    },
    {
      delta node-XY5 : {
        x -3824,
        y 2498
      }
    }
  },
}

```

```

    {
      delta node-XY5 : {
        x -5864,
        y 3933
      }
    },
    {
      delta node-XY5 : {
        x -3771,
        y 2538
      }
    }
  },
  connectsTo {
    {
      connectingLane {
        lane 13,
        maneuver {maneuverStraightAllowed}
      },
      signalGroup 2
    }
  }
},
{
  laneID 22,
  ingressApproach 7,
  laneAttributes {
    directionalUse {ingressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -1444,
        y 386
      }
    },
    {
      delta node-XY5 : {
        x -3837,
        y 2530
      }
    },
    {
      delta node-XY5 : {
        x -5811,
        y 3868
      }
    },
    {
      delta node-XY5 : {
        x -3803,
        y 2600
      }
    }
  }
},
  connectsTo {
    {
      connectingLane {
        lane 14,
        maneuver {maneuverStraightAllowed}
      },
      signalGroup 2
    },
  },

```

```

    {
      connectingLane {
        lane 23,
        maneuver {maneuverStraightAllowed}
      }
    }
  },
  {
    laneID 23,
    ingressApproach 7,
    laneAttributes {
      directionalUse {ingressPath},
      sharedWith {},
      laneType vehicle : {}
    },
    maneuvers {maneuverLeftAllowed, maneuverUTurnAllowed},
    nodeList nodes : {
      {
        delta node-XY3 : {
          x -1233,
          y 651
        },
        attributes {
          dWidth -30
        }
      },
      {
        delta node-XY5 : {
          x -3975,
          y 2603
        }
      },
      {
        delta node-XY5 : {
          x -5048,
          y 3420
        }
      },
      {
        delta node-XY2 : {
          x -836,
          y 110
        }
      }
    },
    connectsTo {
      {
        connectingLane {
          lane 6,
          maneuver {maneuverLeftAllowed}
        },
        signalGroup 5
      },
      {
        connectingLane {
          lane 26,
          maneuver {maneuverUTurnAllowed}
        },
        signalGroup 5
      }
    }
  },
  {
    laneID 24,
    egressApproach 8,

```

```

laneAttributes {
  directionalUse {egressPath},
  sharedWith {},
  laneType vehicle : {}
},
maneuvers {maneuverStraightAllowed},
nodeList nodes : {
  {
    delta node-XY3 : {
      x -585,
      y 1668
    },
    attributes {
      dWidth 30
    }
  },
  {
    delta node-XY5 : {
      x -4937,
      y 3312
    }
  },
  {
    delta node-XY5 : {
      x -5581,
      y 3722
    }
  },
  {
    delta node-XY4 : {
      x -3082,
      y 2363
    }
  }
},
connectsTo {
  {
    connectingLane {
      lane 10,
      maneuver {maneuverStraightAllowed}
    },
    remoteIntersection {
      region 0,
      id 1019
    }
  }
},
{
  laneID 25,
  egressApproach 8,
  laneAttributes {
    directionalUse {egressPath},
    sharedWith {},
    laneType vehicle : {}
  },
  maneuvers {maneuverStraightAllowed},
  nodeList nodes : {
    {
      delta node-XY3 : {
        x -748,
        y 1385
      }
    },
    {
      delta node-XY5 : {

```

```

        x -4915,
        y 3283
    }
},
{
    delta node-XY5 : {
        x -5859,
        y 3926
    }
},
{
    delta node-XY4 : {
        x -2774,
        y 2132
    }
}
},
connectsTo {
    {
        connectingLane {
            lane 11,
            maneuver {maneuverStraightAllowed}
        },
        remoteIntersection {
            region 0,
            id 1019
        }
    }
}
},
{
    laneID 26,
    egressApproach 8,
    laneAttributes {
        directionalUse {egressPath},
        sharedWith {},
        laneType vehicle : {}
    },
    maneuvers {maneuverStraightAllowed},
    nodeList nodes : {
        {
            delta node-XY3 : {
                x -931,
                y 1121
            }
        },
        {
            delta node-XY5 : {
                x -4878,
                y 3209
            }
        },
        {
            delta node-XY5 : {
                x -5809,
                y 3910
            }
        },
        {
            delta node-XY4 : {
                x -2954,
                y 2191
            }
        }
    }
},
connectsTo {

```

```

    {
      connectingLane {
        lane 12,
        maneuver {maneuverStraightAllowed}
      },
      remoteIntersection {
        region 0,
        id 1019
      }
    }
  },
  {
    laneID 27,
    laneAttributes {
      directionalUse {ingressPath, egressPath},
      sharedWith {},
      laneType crosswalk : {hasPushToWalkButton, audioSupport}
    },
    nodeList nodes : {
      {
        delta node-XY4 : {
          x 114,
          y 2225
        },
        attributes {
          dWidth -30
        }
      },
      {
        delta node-XY4 : {
          x 2215,
          y -1389
        }
      }
    },
    connectsTo {
      {
        connectingLane {
          lane 28,
          maneuver {maneuverLeftAllowed}
        },
        signalGroup 14
      }
    }
  },
  {
    laneID 28,
    laneAttributes {
      directionalUse {ingressPath, egressPath},
      sharedWith {},
      laneType crosswalk : {hasPushToWalkButton, audioSupport}
    },
    nodeList nodes : {
      {
        delta node-XY4 : {
          x -1898,
          y -835
        }
      },
      {
        delta node-XY3 : {
          x 936,
          y 1573
        }
      }
    },
  },

```

```
{
  delta node-XY3 : {
    x 849,
    y 1484
  }
},
connectsTo {
  {
    connectingLane {
      lane 27,
      maneuver {maneuverRightAllowed}
    },
    signalGroup 12
  }
},
{
  laneID 29,
  laneAttributes {
    directionalUse {ingressPath, egressPath},
    sharedWith {},
    laneType crosswalk : {}
  },
  nodeList nodes : {
    {
      delta node-XY6 : {
        x 10118,
        y 13872
      }
    },
    {
      delta node-XY4 : {
        x 1909,
        y -1661
      }
    }
  }
}
}
}
}
}
}
}
```